COLORADO DEPARTMENT OF TRANSPORTATION

JOB SAFETY ANALYSIS



Activity Name: Autoclave I	Expansion of Portland C	Cement	Activity Number: ASTM C151				
Activity Description & Pur	pose: Determination of	the autoclave expansion of portland cem	ent by means of a test	on a neat cement paste			
Date Prepared: Typical Equipment					PPE Required		
		Typical Crew Size:	Typical Material		1- Hard toe boots 2- Heat		
Description See associated test procedure	Class Code	(Crew sizes may vary due to different conditions throughout the state).	Description Portland Cement Water	Class Code	resistant gloves 3. Eye protection		
Sequence of Job Tasks	Potential Hazards	Safe .	Never				
1- Mix cement paste	1- Hand injury	Sale	Job Procedures		INCVCI		
2- Mold specimen	1- Foot injury	1- Wear hard toe boots					
3- Demold specimen	1- Foot injury	1- Wear hard toe boots					
4- Run specimen in autoclave	1- Burn injury 2- Explosion Injury	1- Wear heat resistant gloves 2- Wear eye protect					
5- Remove specimin from autoclave	1- Burn injury	1- Wear heat resistant gloves 2- Wear eye protect					
6- Determine specimin length							
	_						

COLORADO DEPARTMENT OF TRANSPORTATION

JOB SAFETY ANALYSIS



Activity Name: Autoclave E	xpansion of Portland C	Cement	Activity Number: AS	Activity Number: ASTM C151		
Activity Description & Purp	oose: Determination of	the autoclave expansion of portland ceme	ent by means of a test o	on a neat cement paste.		
Date Prepared:					PPE Required	
Typical Equipment		Typical Crew Size:	Typical Material		1- Hard toe boots 2- Heat	
Description	Class Code	(Crew sizes may vary due to different conditions throughout the state).	Description	Class Code	resistant gloves 3. Eye protection	
See associated test procedure			Portland Cement Water		protection	
		2				
Sequence of Job Tasks	Potential Hazards	Safe Job Procedures			Never	
Notes and Specifications Instructions			Other Related Resources			

